





State Water Resources Control Board

November 3, 2017

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 7928 4222

Mr. Manuel Azevedo
Equipment Maintenance Supervisor
City of Sacramento
5303 Franklin Boulevard
Sacramento, CA 95820
mazevedo@cityofsacramento.org

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT CITY OF SACRAMENTO ROONEY POLICE GARAGE, 5303 FRANKLIN BOULEVARD, SACRAMENTO

Dear Mr. Azevedo:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on October 25, 2017, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Testing Records Onsite – The 2017 Annual Monitoring Certification was not onsite at the time of inspection.	North and South Unleaded	October 25, 2017	Ongoing	23 CCR 2712(b)
2	Failure to Provide Valid State Board of Equalization (BOE) Registration Number – The BOE number provided in CERS is not valid.	North and South Unleaded	October 25, 2017	Ongoing	H&SC 25286(c)(9)
3	Failure to Tag Monitoring Equipment – The line leak detector in both unleaded turbine sumps are not tagged with a certification sticker.	North and South Unleaded	October 25, 2017	Ongoing	23 CCR 2638(f)

Office of Enforcement | 801 K Street, Suite 2300 | Sacramento, CA 95814 | 916.341.5272

FELICIA MARCUS, CHAIR | EILEEN SOBECK, EXECUTIVE DIRECTOR

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Monitor Product Piping – The sensors in the North and South unleaded fill sumps are unable to detect a leak at the earliest opportunity because the sensors are not in a true vertical position at the lowest point in the sump.	North and South Unleaded	October 25, 2017	October 25, 2017	23 CCR 2630(d)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Sacramento County Environmental Management Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations has been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Mr. Joseph Lovesee
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
joseph.lovesee@waterboards.ca.gov

Local CUPA

Ms. Jennea Monasterio
Environmental Scientist
Sacramento County Environmental
Management Department
10590 Armstrong Avenue
Mather, California 95655
monasterioj@saccounty.net

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

UST Enforcement Unit

Office of Enforcement

CC:

See next page.

cc: (via email only)

Ms. Jennea Monasterio
Environmental Specialist
Sacramento County Environmental
Management Department
monasterioj@saccounty.net

Mr. Brion McGinness
Environmental Specialist
Sacramento County Environmental
Management Department
mcginnessb@saccounty.net